


L Number	Hits	Search Text	DB	Time stamp
-	290	244/129.1.cccls.	USPAT; US-PGPUB	2004/01/06 15:22
-	27	244/129.1.cccls. and cabl\$	USPAT; US-PGPUB	2004/01/06 14:55
-	8	(("6293874") or ("5678617") or ("5971829") or ("5934226") or ("4666425") or ("6179774") or ("6113940") or ("4681244")).PN.	USPAT; US-PGPUB	2004/01/07 08:57
-	326	244/131.cccls.	USPAT; US-PGPUB	2004/01/07 10:49
-	14	244/131.cccls. and cabl\$	USPAT; US-PGPUB	2004/01/07 10:51
-	187	244/125.cccls.	USPAT; US-PGPUB	2004/01/07 10:51
-	28	244/125.cccls. and (cabl\$ or conduit\$)	USPAT; US-PGPUB	2004/01/07 10:54
-	77	244/118.2.cccls.	USPAT; US-PGPUB	2004/01/07 10:56
-	554	244/121.cccls.	USPAT; US-PGPUB	2004/01/07 10:56
-	53	244/121.cccls. and (cabl\$ or conduit\$)	USPAT; US-PGPUB	2004/01/07 11:04
-	478	244/\$.cccls. and wiring	USPAT; US-PGPUB	2004/01/07 11:05
-	1401	244/\$.cccls. and (wiring or network)	USPAT; US-PGPUB	2004/01/07 11:05
-	530	(244/\$.cccls. and (wiring or network)) and instal\$	USPAT; US-PGPUB	2004/01/07 11:39

See also google search attached



Web · Images · Groups · Directory · News

Searched the web for **Running Cable**.

Results 1 - 10 of about 4,110,000. Search took 0.18 seconds.

Category: [Shopping](#) > [Vehicles](#) > [Parts and Accessories](#) > [Exterior](#) > [Lighting](#)

Dummies: Running Cable for Your Home Network

Home > Advanced Computing > Networking > **Running Cable** for Your Home Network. ... Then run the **cable** along the baseboard to the computer. ...

www.dummies.com/WileyCDA/DummiesArticle/id-2268.html - 31k - [Cached](#) - [Similar pages](#)

Hometime - How-To - Project Help - Electrical

... Pg 3. Electrical **Running Cable**. **Running** electrical **cable** is simple in theory: pull it through holes in the framing from a junction box to the service panel. ...

www.hometime.com/Howto/projects/electric/elec_3.htm - 16k - [Cached](#) - [Similar pages](#)

[UCLA-LUG] Running Cable Outside

[UCLA-LUG] **Running Cable** Outside. ... Previous message: [UCLA-LUG] **Running Cable** Outside; Next message: [UCLA-LUG] **Running Cable** Outside; ...

linux.ucla.edu/pipermail/linux/2000-November/004193.html - 4k - [Cached](#) - [Similar pages](#)

[UCLA-LUG] Running Cable Outside

[UCLA-LUG] **Running Cable** Outside. Denis ... 0800: Previous message: [UCLA-LUG] **Running Cable** Outside; Next message: [UCLA-LUG] Chat Reminder; ...

linux.ucla.edu/pipermail/linux/2000-November/004195.html - 3k - [Cached](#) - [Similar pages](#)

[More results from linux.ucla.edu]

RUNNING CABLE

... **RUNNING CABLE**. ... Subject: **RUNNING CABLE**. ... PacBell.COM. Next by Date: **RUNNING CABLE**, GAMMA!GAMMA!steve@gammacc.attmail.com. Previous by ...

lists.contesting.com/archives/html/CQ-Contest/1994-06/msg00029.html - 12k - [Cached](#) - [Similar pages](#)

RUNNING CABLE

... **RUNNING CABLE**. ... Subject: **RUNNING CABLE**. ... Previous by Date: **RUNNING CABLE**, GAMMA!GAMMA!steve@gammacc.attmail.com.

Next by Date: Help, cmschonewaldcox@ucdavis.edu. ...

lists.contesting.com/archives/html/CQ-Contest/1994-06/msg00114.html - 12k - [Cached](#) - [Similar pages](#)

[More results from lists.contesting.com]

Computing.Net - Trouble **running cable** over 50ft

... Subject: Trouble **running cable** over 50ft. Original Message. ... Name: Brian Date: October 26, 2003 at 14:41:55 Pacific Subject: Trouble **running cable** over 50ft. ...

wwwcomputing.net/networking/wwwboard/forum/17361.html - 17k - [Cached](#) - [Similar pages](#)

[cable] Problem **running Cable** compiled with GCC 3.2 on HP-UX 11

[cable] Problem **running Cable** compiled with GCC 3.2 on HP-UX 11. ... Previous message:

[cable] Problem **running Cable** compiled with GCC 3.2 on HP-UX 11; ...

public.kitware.com/pipermail/cable/2002-December/000040.html - 6k - [Cached](#) - [Similar pages](#)

[cable] Problem **running Cable** compiled with GCC 3.2 on HP-UX 11

... [cable] Problem **running Cable** compiled with GCC 3.2 on HP-UX 11. Steven

Levitt slevitt@siac.com Mon, 23 Dec 2002 13:31:47 -0500: Previous ...
public.kitware.com/pipermail/cable/ 2002-December/000039.html - 39k - [Cached](#) - [Similar pages](#)
[[More results from public.kitware.com](#)]

Self Help Forums - kitchen reno, running cable for kitchen ...

#1. 01-03-2004, 09:43 AM. Smithy. Junior Member. Join Date: Dec 2003. Posts: 8. kitchen
reno, **running cable** for kitchen circuits. Best wishes for the New Year to all! ...

[www.selfhelpforums.com/ showthread.php?goto=newpost&t=342](http://www.selfhelpforums.com/showthread.php?goto=newpost&t=342) - 47k - [Cached](#) - [Similar pages](#)

Google ►

Result Page: 1 [2](#) [3](#) [4](#) [5](#) [6](#) [7](#) [8](#) [9](#) [10](#) [Next](#)

Dissatisfied with your search results? [Help us improve.](#)

[Google Home](#) - [Advertise with Us](#) - [Business Solutions](#) - [Services & Tools](#) - [Jobs, Press, & Help](#)

©2004 Google


[Advanced Search](#) [Preferences](#) [Language Tools](#) [Search Tips](#)

[Web](#) · [Images](#) · [Groups](#) · [Directory](#) · [News](#)
Searched the web for **Running Cable aircraft**.

Results 31 - 40 of about 126,000. Search took 0.48 seconds.

Supply

... antenna to the receiver when a long **cable** run (>50 Feet ... Ideal for aircraft or bench

testing applications ... it will prevent excessive voltage from **running** down the ...
www.navtechgps.com/supply/equipment.asp?Line=antenna - 24k - Jan 13, 2004

- [Cached](#) - [Similar pages](#)

Sponsored Links

WebRiggingSupply.com

Lifting, Pulling, Towing, Stowing?
 You've come to the right place.

www.WebRiggingSupply.com
 Interest:

Airliners.net Aviation Forum - Cable TV Questions

... If you see ghosting on broadcast channels that's a sign you have too much wiring.

Also if **running cable** internet this can cause reduced bandwidth. ...
www.airliners.net/discussions/non_aviation/read.main/473881/ - 32k - [Cached](#) - [Similar pages](#)

Aircraft Cable

Huge Variety of Calibrators & More Supplies - Search Thomas Register!

www.ThomasRegister.com
 Interest:

[PDF] PBS-4100 Aircraft Balancing - PDF

File Format: PDF/Adobe Acrobat - [View as HTML](#)

... yourself with the PBS-4100 without **running** an engine. ... MTI can provide cable sets

for any type of hookup ... directly to engine sensors or via aircraft wiring (AVM ...

www.mtiinstruments.com/pdf/pbs.pdf - [Similar pages](#)

GBG Industries

Wire rope, steel cable assemblies.
 Factory direct.

www.gbgindustries.com
 Interest:

Rotax aircraft engine troubleshooting for ultralights, ultralight ...

... &^%\$#@ Rotax, Hirth, Cuyuna, Kawasaki ultralight **aircraft** engine won ... low speed jet

C. replace throttle **cable** free up ... Is fuel **running** out overflow tubes on side ...

www.ultralightnews.com/enginetroubleshooting/start.htm - 49k - [Cached](#) - [Similar pages](#)

Cable Assembly Mfgs List

Full list of companies with preview ads, descriptions, and site links.

www.wire-rope.org

Interest:

[See your message here...](#)

Intelligence & Information Systems

... with the RSDS installed in the **aircraft** or mounted on ... use with Intel compatible processor PCs, running Microsoft DOS ... Laminated instructions, Reprogramming **Cable**. ...

www.esd.sri.com/i2s/mlv_kits.html - 26k - [Cached](#) - [Similar pages](#)

[FAQ: Aircraft Check and Quick EEPROM] - HowardForums

... keep all of the "How do I disable **aircraft** check" threads ... in browther/use it like a disk without **running** Data Suite ... I would like to attach the **cable** and see the ...
www.howardforums.com/archive/topic/272137-1.html - 9k - [Cached](#) - [Similar pages](#)

broadband » Forums » Cogeco » Cable Splitter

... - If this **aircraft** was alive she'd be crying supersonic tears now. ... There already existed a **cable** line **running** up to the office, where we wanted internet ...

www.dslreports.com/forum/remark,8803598~mode=flat - [Similar pages](#)

Ground-Link Installation

... You will need to **run** the coaxial **cable** from the ... Perform this test with the telephone **cable** disconnected. ... radio (or have someone key an **aircraft** radio) four ...

www.avtech-marketing.com/install.html - 18k - [Cached](#) - [Similar pages](#)

[ansidocstore: Department: 'DIN ICS 49 Aircraft and Space Vehicle ...](#)
... **aircraft** electrical systems; testing of electrical **cables** installed in **aircraft** (FOREIGN STANDARD ... Aerospace; wire thread inserts; free **running** or screw ...
www.ansi.org/ansidocstore/dept.asp?dept_id=3032 - 101k - [Cached](#) - [Similar pages](#)

Cap 528 s 9 Cable programmes

... (2) The following are excepted from the definition of "cable programme service": ... or in 2 or more vehicles, vessels, **aircraft** or hovercraft ... (f) the **running** by a ...

www.justice.gov.hk/blis.nsf/0/eb59351f7eaba0aa482564dc00270b93?OpenDocument - 17k - [Cached](#) - [Similar pages](#)



Result Page: [Previous](#) [1](#) [2](#) [3](#) [4](#) [5](#) [6](#) [7](#) [8](#) [9](#) [10](#) [11](#) [12](#) [13](#) [Next](#)

[Google Home](#) - [Advertise with Us](#) - [Business Solutions](#) - [Services & Tools](#) - [Jobs, Press, & Help](#)

©2004 Google



Advanced Search Preferences Language Tools Search Tips

"running cable" in an aircraft

Google Search

The following words are very common and were not included in your search: **in an.** [\[details\]](#)

Web · Images · Groups · Directory · News

Searched the web for "running cable" in an aircraft. Results 1 - 10 of about 145. Search took 0.19 seconds.

Wave Wireless Networking, a division of SPEEDCOM Wireless ...

... This is the situation faced by Experimental Aircraft Association (EAA), Network Administrator ... of the nature and size of the location, **running cable** or fiber ...
www.wavewireless.com/classroom/userprofiles/EAUp.htm - 6k - [Cached](#) - [Similar pages](#)

Sponsored Links

Aircraft Cable

Huge Variety of Calibrators & More Supplies - Search Thomas Register!
www.ThomasRegister.com
 Interest: [\[redacted\]](#)

Airliners.net Aviation Forum - Cable TV Questions

... If you see ghosting on broadcast channels that's a sign you have too much wiring.
 Also if **running cable** internet this can cause reduced bandwidth. ...
www.airliners.net/discussions/non_aviation/read.main/473881/ - 32k - [Cached](#) - [Similar pages](#)

GBG Industries

Wire rope, steel cable assemblies. Factory direct.
www.gbgindustries.com
 Interest: [\[redacted\]](#)

ME: Loeb Mainstage

... a number of winches in the grid are set up to drop **aircraft** cable down to ... directly to the T beam over the rigging channel (rather than **running cable** through a ...
theater.harvard.edu/jobs/me/mainstage.html - 15k - [Cached](#) - [Similar pages](#)

Cable Assembly Mfgs List

Full list of companies with preview ads, descriptions, and site links.
www.wire-rope.org
 Interest: [\[redacted\]](#)

[See your message here...](#)

[PDF] The PREMIUM KIT WITH THE STRAIGHT LINE CLAMP Premium Kit ...

File Format: PDF/Adobe Acrobat - [View as HTML](#)

... 2. Holding the clamp parallel to the up-running **cable**, run the #12 x 3 ... die-cast)
 (2) Cable assemblies - 9' x 1 / 8 " diameter (galvanized **aircraft** cable) (2 ...
winss.com/PDFS/premium_cable.pdf - [Similar pages](#)

[PDF] The PREMIUM KIT WITH THE STRAIGHT LINE CLAMP Premium Kit ...

File Format: PDF/Adobe Acrobat - [View as HTML](#)

... cast) (2) Cable assemblies - 9' x 1 / 8 " diameter (galvanized **aircraft** cable)
 Includes ... 2. Holding the clamp parallel to the up-running **cable**, run the #12 x 3 ...
winss.com/PDFS/premium_rod.pdf - [Similar pages](#)

SCS ATCALS Maintenance

... pass information between the Supervisor of Flying (SOF) and the soaring **aircraft**. ... Work included mounting the antenna and **running cable** from the roof to their ...
www.usafa.af.mil/sc/scs/scsmr/index_main.htm - 10k - [Cached](#) - [Similar pages](#)

Wiring new house for satellite tv

... If you're doing it yourself, double **running cable** to the outlet box, and only ... Unless you are next to a TV transmitter or an **aircraft** radar installation, etc ...
ths.gardenweb.com/forums/load/electronics/msg0917582613283.html - 18k - [Cached](#) - [Similar pages](#)

WLANA The Learning Zone for Wireless Networking

... was extremely expensive, especially when it involved historical buildings **running cable** through ceilings ... and the outside work area of an **aircraft** manufacturer. ...
wlana.org/learn/roi.htm - 27k - [Cached](#) - [Similar pages](#)

[PDF] Wireless Local Area Networking: ROI / Cost-Benefit Study Executive ...

File Format: PDF/Adobe Acrobat - [View as HTML](#)

... was extremely expensive, especially when it involved historical buildings—**running cable** through ceilings ... and the outside work area of an aircraft manufacturer ...

www.enterasys.com/products/wireless/WLANASTUDY-Ex.pdf - [Similar pages](#)

[Spy Company Video Surveillance. Wireless Video Surveillance ...](#)

... us at 1-888-477-9779 for extended range options) without **running cable**. ... application (investigative reporting, insurance investigation, etc.), R/C aircraft, R/C ...

www.spycompany.com/video.htm - 37k - [Cached](#) - [Similar pages](#)

Google ►

Result Page: 1 2 3 4 5 6 7 8 9 10 [Next](#)

Dissatisfied with your search results? [Help us improve.](#)

[Google Home](#) - [Advertise with Us](#) - [Business Solutions](#) - [Services & Tools](#) - [Jobs, Press, & Help](#)

©2004 Google